## Joe Cavallaro 2425 Ave. A Council Bluffs, Iowa



Front of House




West, Rear of house



Front, West Corner of House

West Side of House



Damaged Gutter and Downspout



West Side of Porch Area



Garage North Side



Garage, West Side



Tomato Plants, shredded



Shredded Remains of Tomato Plants



Lawn Ornament (Glass Globe Broken)





Gazebo Roof Damage



Gazebo from inside, looking west



Broken Party Lights, shades missing & broke



Damaged Canopy on Glider Swing



Roof Gravel and house paint from downspout



Deck floor and railing, speckled and dented from hail



Trimmed Branches that damaged Gutter and Downspout



Hey! Avenue A is a ONE WAY STREET!